



March 17, 2000

BOEING Realty Corporation 4060 Lakewood Blvd. 6<sup>th</sup> Floor Long Beach, CA 90808-1700

Project:

Torrance Harbor Gateway 1540-1580 Francisco Street

Torrance, CA

Law/Crandall Project 70347-0-0001

Dear Mr. Stavale:

Law/Crandall has performed the inspection services for reinforced concrete at the above referenced project. Copies of the daily field reports of the required inspections performed on March 1, 2 and 3, 2000 are attached for your review.

Edward A. Salazar

roject Engineer

Respectfully submitted,

LAW/CRANDALL

A DIVISION OF LAW ENGINEERING AND ENVIRONMENTAL SERVICES, INC.

David Wilson, P.E..

Senior Engineer

I:\Inspection Reports\70347\00001in3.doc

Satiseia Wyrn

Attachments

Distribution:

**BOEING** 

Attn: Mr. Johnny Marasco

A Division of Law Engineering and Environmental Services, Inc. 731 East Ball Road, Suite 104
Anaheim, CA 92805-5145
714-776-9544 • Fax 714-776-9541

## LAW / CRANDALL

200 CITADEL DRIVE • LOS ANGELES, CA 90040 (213) 889-5300 • FAX (213) 721-6700

JOB . 703	47-	0-	0	70	·/
	3				

DAIL	/ FIEL	D REPO	DRT	(	CONSECUTIVE	Į.	t			OR WEEK NOING		3/3	10	) 0
		RFORM SPECIAL		REINFOR	CED CONCRETE		STRUC	CT. STEE	L ASSEME	BLY	SPRAY	-APPLIED FIREP	IOOFING	3
INSPECTION	N IN THE CATE	GORY CHECKE	D.		ESSED CONCRETE		DEEP	FOUNDA'	TION					
					CED MASONRY		OTHE	R			.,			I
JOB ADDRES	ss	<u></u>				<u>(4)</u>	BUILDING	PERMIT	NUMBER	(1	D PLAN F	HLE NUMBER		<u> </u>
154	0-15	<u>80 Fr</u>	RANCIS	500 50	T, TORRA	NŒ	4902	~ ٥	4000	0-03				~
	PROJECT NAM	ie Pro	TO II FI	ENCE)	NALL	(3)	APPLICATI	ON NUM	BER					12
BOE				YAW	CENTER									
CONSTR. MA	ITL (TYPE, GI		6 DESIGN	0	SOURCE OF MFGR.	(3)	ARCHITEC	T						13
ASI	1 A615		0											
DESCRIBE M	IAT'L. (MIX DE	SIGN, RE-BAR GI	RADE & MFGR.,	WELD-ROD, ET	·C.)	9	ENGINEER		a	ZWZ	50 V	di C		<b>(9)</b>
							GENERAL			- MA	N/	113		<b>(5)</b>
							RI	SYI.	FY.	CONS	57R ()	CTION		
				······································		•	CONTR. DO			ORK	<u> </u>	rRE	BAR	<b>6</b>
							B	N	E. 5	SMI	TH IN	IC KINGI	NEER	JUE
INSPEC. ①	ARRIVAL (B)	DETAILED	LOCATION OF V	VORK INSPECT	EO, TEST SAMPLES	TAKEN,	WORK REJE	CTED, JO	B PROBLI	MS, PROGE	RESS, REM	ARKS, ETC.		(19)
DATE	DEPARTURE TIME	REPORT OF WORK INSPECTED		•										
711			1000	<u> </u>									- 0-	<del></del>
3/1/00	Tam	] ]	NSHEO!	P R	INFORC	EM	ENT	DE	171 A3	REI	7 E	GRAD		747
1	3300	CAG	89 CE	HISTR	DOTED.	#	INST	21	ED	FRE	The	PILE#	81-9	71
****		250	06.4.A.11	6 61			2 , 12					400		-4
		TV	1711	19 5									1CR#	
		GRA	PFB	EAM	W/8 -	#6	6	MT.	8	# 3	4109	SED ST	IRRU	<u>PS</u>
		@3"	O.C.	AIT	took L	0/2	TION							
				7	1001	· • ·	1,013							
						·				<del></del>	<del></del>			
											_			
<del></del>														
					•									
				<del> </del>										
			····											
														1
			-+											
			٠.			·····								
			·											
			~~~~									·		
,														
				·								, <u></u>		@
			OUR KNOWLEDG		INSPECTOR	TECHN	ICIAN DY	4161	1 7	17	OHL		· · · ·	- "
		MS TO THE APPE APPLICABLE WO	ROVED PLANS AI XKMANSHIP	AD	SIGNATURE			2-	1	<u> </u>	-d-	0010		
		RM BUILDING CO			DATE SIGN	ED 3	/ 1 / 0	D PEGI	STRATION	NO. BC	X99.	3849		
			REVIEWED	BY			mu	me (						

## LAW / CRANDALL

200 CITADEL DRIVE • LOS ANGELES, CA 90040 (213) 889-5300 • FAX (213) 721-6700

JOB # 70347-0-000/
TODAY'S DATE 3 2 00

DAILY FIELI	REPORT	GONSECUTIVE REPORT NO.	2	② FOR WEEK ENDING	3/3	100
I AM AUTHORIZED TO PER INSPECTION IN THE CATE		MEINFORCED CONCRETE	STRUCT, STE		SPRAY-APPLIED FIREPROO	FING 3
		PRE-STRESSED CONCRETE  PREINFORCED MASONRY	OTHER	ATION		
JOB ADDRESS			3) BUILDING PERMIT	NUMBER	(0) PLAN FILE NUMBER	• <b>1</b>
	SO FRANCIS	CO ST. TORRANCE	3/1	40000-0	<u> </u>	₩
OWNER OR PROJECT NAME	PROTO 11 FE	MCE WALL (	APPLICATION NUM			12
BOEING H	AREOR GRIE	WAY CENTER				
CONSTR. MAT'L. (TYPE, GR	- COENCIL	OF MEGR.	ARCHITECT .			13
	IGN, RE-BAR GRADE & MFGR., N	MELD-ROD, ETG.)	9) ENGINEER			<u>@</u>
				CE BAN	DER VIS	
			GENERAL CONTRA	EY CON	STRIVTION	(9)
:	•		CONTR. DOING RE	PORTED WORK	NC ENGINEE	
INSPEC- (7) ARRIVAL (18)	DETAILED LOCATION OF W	VORK INSPECTED, TEST SAMPLES TAKE				(1)(1)
TION TIME. DEPARTURE	REPORT OF WORK INSPECTED	TOTAL DESIGNATION OF THE PERSON OF THE PERSO	N. HUMANICO DO CO.			•
3/2/00 7am	INSPECTE	D REINFORCET	YENT FO	RGRAPE	BEAM CAGI	55
3300	CONSTRUC	TED & INSTAL	HED FRO	DM PILE	+66-31	
	SICMU RET	ZINING WALL	POWELS	& PROT	OIL 6" WALL	
	ROD INSTA	LLED PER DET	HILS SK	1 \$ 5	K2.	
	ALL PROTO	I ROD FOR	8' H19H	WALL G	B 51-4" a.	c.
	&8'CMU	RETAINING # 5	S @ 48'	0.0.0	UTSIDE FAC	£
	& RETAIN!	19 FACE 5'-	4" UPT	0 6' F	HACED #56	9
	24" 0,0.	4' RETAININ	91#56	48" 0	).c.	
	COMPROS	JOINTS @ 36	510.6.	E WAL	V HEIGHT 4	MUGET
		LION SHE		20 CHOTT	K SIPES	
:	PROTO JE R	OD £ 2 #5,	4"0.0	BOTH	SIDES RETA	IMING
	WALK.					
<u> </u>	INSPECE	ED CONCRETE	PLACE	DE ME	CHANICALLY	
		STED @ GRAD				
	15510	F3 CYLINDERS	OF MIX	< #4M8	B20, 2500	2 Bi
	TAKEN FO	R 20YDS PLA	KED BY	MESTSI	DE CONC.CO	· INC.
	<u>'`</u>					
	***************************************		HNICIAN DW	CIH BIT	7-104N	
	), TO THE BEST OUR KNOWLEDG MS TO THE APPROVED PLANS AN		HNICIAN		VVI.	
SPECIFICATIONS, AND THE PROVISIONS OF THE UNIFOR	APPLICABLE WORKMANSHIP RM BUILDING CODE.	DATE SIGNED	3 2 60/60	ISTRUTION NO.	2CR99-384	1
		REVIEWED BY		trust		

## LAW/CRANDALL

200 CITADEL DRIVE • LOS ANGELES, CA 90040 (213) 889-5300 • FAX (213) 721-6700

JOB . 70347-C	7-0001	
TODAY'S DATE		

DAILY FIELD REPORT	TEPORT NO.	3 @ ENDING 3 /3 /6	0
! AM AUTHORIZED TO PERFORM SPECIAL	THEINFORCED CONCRETE	STRUCT. STEEL ASSEMBLY SPRAY-APPLIED FIREPROOFING	<b>③</b>
INSPECTION IN THE CATEGORY CHECKED.	PRE-STRESSED CONCRETE	DEEP FOUNDATION	
	REINFORCED MASONRY	OTHER	
JOB ADDRESS	يسد ودده كالمداسد المساهر	BUILDING PERMIT NUMBER (1) PLAN FILE NUMBER	•
OWNER OR PROJECT NAME PROTO ILE	ENCE WALL	99020-4000-039B	@
BOGING, HARBOR GATEWI	Y CENTER		9
CONSTR. MAT'L. (TYPE, GRADE, ETC.) 6 DESIGN	SOURCE	(8) ARCHITECT	13
A9TM A615 GR 60			
DESCRIBE MAT'L (MIX DESIGN, RE-BAR GRADE & MFGF	i., WELD-ROD, ETC.)	TAKE BANDER VIS	(4)
		GENERAL CONTRACTOR	<b>®</b>
		BAYLEY CONSTRUCTION	
<u>.</u>		BEN E. SMITH INC. ENGINEERING	16
			====
INSPEC- (7) ARRIVAL (B) DETAILED LOCATION OF TIME. DEPARTURE OF WORK INSPECTED	F WORK INSPECTED, TEST SAMPLES T	AKEN, WORK REJECTED, JOB PROBLEMS, PROGRESS, REMARKS, ETC.	(9)
1 1 1 1		MENT FOR GRADE BEAM CAGES	
3-30 A CONSTRUC	ted e instal	LED FROM PILE # 34-66.	
· I	•	PLACED & MECHANICALLY CONSOL	-1-
	· · · · · · · · · · · · · · · · · · ·	FROM PILE \$ 59-73.	
l l		Zrof MIX#4MRBZOZBOOP	
PT WEST	SIDE CONC. C	O. INC. TAKEN FOR 20 PD. PLACE	P
			-
	<b>*</b>		
			$\neg \neg$
UNLESS OTHERWISE NOTED, TO THE BEST OUR KNOWLE OBSERVED WORK CONFORMS TO THE APPROVED PLANS		ECHNICIAN DIMIGHT PITZSOHN	_ @
SPECIFICATIONS, AND THE APPLICABLE WORKMANSHIP PROVISIONS OF THE UNIFORM BUILDING CODE.	DATE SIGNED	3 / 3 / 00 BEGISTATION NO. BL. 899 3849	
	REVIEWED BY		